



### Order #XXXXX MOD-1447 Charging Station


Item	Qty.	Description
1	1	26" x 26" x 3" Base
2	1	57.4675" RR91 Post
3	1	25" x 25" Counter Bottom
4,4A	3,1	6" Z45 Horizontal Extrusion
5	1	26" x 26" x 5" Counter Top
	1	Bracket




#### Steps:


- 1) Attach base [1] to post [2], using bolt, routing power cord thru holes.
- 2) Slide counter bottom [3] over post [2]. NOTE: Counter bottom will be "free floating" until counter top is attached.
- 3) Connect extrusions [4,4A] to post [2]. Note: Extrusion [4A] is permanently attached to underside of Counter Top.
- 4) Slide counter top [5] over post [2], connect power cords to USB ports & power outlets, then attach to counter bottom [3] using bolts to L-brackets.
- 5) Install header to top of post [2], using bolt.
- 6) Connect transformer to lights in header. See Light to Transformer Connection detail and photos below.
- 7) Attach graphics to standoff barrels on front & back of header, using standoff caps.








**Completed Assembly** 



Underside View of Counter Top









## General Setup Instructions


- Read entire setup instruction manual prior to unpacking parts and pieces.
- The setup instructions are created specifically for this configuration.
- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.

# Cleaning & Packing


- For Cleaning Metal, Plex, & Laminate Parts: Use a MILD NON-ABRASIVE cleanser and soft cloth/paper towel to clean all surfaces.
- Keep exhibit components away from heat and prolonged sun exposure. Heat and UV exposure will warp and fade components.
- Retain all provided Packing Materials. All provided packing materials are for ease of repacking & component protection.

## Disassembly

- For loss prevention, tighten all setscrews and locks during disassembly




Hex Tool - Essential for Assembly




Part Identification - Numbering



# MARNING



Spline Connection



**Base Plate & Extrusion Connection** 









LADDERS OR LIFTS MAY BE REQUIRED



**ALL CONNECTIONS MUST** BE TIGHTLY SECURED



**Extrusion & Lock Connection** 



Engaged Lock

