
■DESIGNSI

Order #XXXXX **MOD-1267 Pedestal**


Item	Qty.	Description
1	1	38" Vertical Extrusion w/ Door Hinges
2	1	38" Vertical Extrusion w/ Door Stop
3	1	38" Vertical Extrusion
4	1	38" Vertical Extrusion
5	2	22.0197" Horizontal Extrusion
6/6A	2/2	12.5" Horizontal Extrusion
7	2	25.639" Curved Extrusion


Steps


- 1) Attach horizontal extrusions [5] & [7] between assemblies [1,4,6,6A] & [2,3,6,6A].
- 2) Connect vertical extrusions [3A] & [4A] on top of horizontal extrusion [7].
- 3) Attach assembled door to vertical extrusion [1]. See Door Connection detail.
- 4) Slide Infill between verticals [3A] & [4A].
- 5) Attach upper horizontal extrusions [5] & [7] between assemblies and on top of Infill.
- 6) Connect Velcro on shelf supports to inside of assemblies then set shelf on top of supports.
- 7) Place pedestal top on assembled pedestal. See Pedestal Top Attachment detail.




Completed Pedestal Assembly

















General Setup Instructions

- Read entire setup instruction manual prior to unpacking parts and pieces.
- The setup instructions are created specifically for this configuration.
- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.



Hex Tool - Essential for Assembly



Part Identification - Numbering




Cleaning & Packing

- For Cleaning Metal, Plex, & Laminate Parts: Use a **MILD NON-ABRASIVE** cleanser and soft cloth/paper towel to clean all surfaces.
- Keep exhibit components away from heat and prolonged sun exposure.
 Heat and UV exposure will warp and fade components.
- Retain all provided Packing Materials.
 All provided packing materials are for ease of repacking & component protection.




- For loss prevention, tighten all setscrews and locks during disassembly




Spline Connection

Extrusion & Lock Connection



Base Plate & Extrusion Connection



Engaged Lock



DO NOT USE POWER TOOLS



LADDERS OR LIFTS MAY BE REQUIRED



ALL CONNECTIONS MUST BE TIGHTLY SECURED

